WA 875649

LANDLORD/HOMEOWNER GAS SAFETY RECORD



This record can be used to document the outcomes of the checks and tests required by The Gas Safety (Installation and Use) Regulations. Some of the outcomes are as a result of visual inspection only and are recorded where appropriate. Unless specifically recorded no detailed inspection of the flue lining, construction or integrity has been performed. Registered Business/engineer details can be checked at www.gassaferegister.co.uk or by calling 0800 408 5500,

Gas Safe is a registered trade mark of HSE and is used under licence												
Details of Registered Business	Appliance Details											
Gas Safe Register No 2007		Location of		Type	Manufacturer		Model		Owned by Landlord	Inspected	Type of	
Registered Engineer's Name W BROOKS	1	KITHEN		COMBI	WORLESTER.		25 I		/Homeowner Yes/No	Yes/No	PSF	
Gas Safe Register Licence Number 4788459	2	KIRTEN		HOB	V VOCAC SIER,		25.1		UL	7	KSF	
Business D. PRICE PLUMBING 1 HEATING	3			11013								
Address CILMERI, ABERCANAID	4 -											
MERTHUR TUDFIL.	Inspection Details											
Postcode CF 48 143 Contact No 07786106272		Operating	Op	eration of	Ventilation	Visual condition	Flue	Combustion	Service	d	SAFE	
		pressure in mbar and/or heat input kW/h or Btu/h		ty device(s) ss/Fail/NA	satisfactory Yes/No	of flue and termination Pass/Fail/NA	operation checks Pass/Fail/NA	analyser reading (if applicable)		s/No TO USE Yes/No		
Details of Site	1	23 P FW		3	7	P	P	0.0004	7 N		121	
Name (Mr/Mrs/Miss/Ms) D WATKING Address DOCAFIELD ST	2	20.5 Mg		P	7			_	N		松	
CATHAYS	3 4											
CARDIFF												
	Any								classification Warning/Advice Record insert form serial No*			
Postcode CF 24 4 @3	1	1										
Contact No		3										
	4								-			
Details of Landlord/Homeowner (or agent where appropriate)	Ren	Remedial Action Taken numbering should correspond to defects above.										
Name (Mr/Mrs/Miss/Ms) D WATKINS	1									*		
Address 9 CUPLEW CLOSE	2											
NOTTAGE	3											
0.671 0.00	Details of Work carried out											
Postcode CF36 3QB									,	•		
Contact No 07977906186												
Number of Appliances tested: 2									* Refer to separa	te Warning	/Advice Notice	
Outcome of gas installation pipework visual inspection? Pass			ord is	sued by: Sigr	ature	W Brook	29			ATTE	NTION	
Outcome of gas supply pipework visual inspection?			Nan	ne	W (shoots				Next	safety	

check due by:

Is the Protective Equipotential bonding satisfactory?

Outcome of gas tightness test?

Is the Emergency Control Valve access satisfactory?



Date appliance(s)/flue(s) checked

Received by: Signature

9=2=21

Tenant/Landlord/Homeowner/Agent

Top Copy - Landlord/Homeowner/Managing Agent Green Copy - Tenant Yellow Copy - Registered Business